

The Flood

January 2, 1979

In the early morning hours, a sprinkler "T" connection fractured and sent 300,000 gallons of water from above the round fireplace throughout the club house.



main break sighted above fireplace.




3 other t's broke after first water test.



men's locker room w/ collapsing ceiling tile & insulation.



due to so much water in the ceiling, drapes & rod were pulled away from the wall.



insulation,



insulation,



& more insulation!



connection broke in pro shop too.




carpet is being removed & replaced.



couch is being replaced.



thorough inspection of wiring was conducted.



fluorescent ballast became wet & will be replaced as needed.



check your lockers for
mildewed clothing.



all wall paper was ruined.



sagacious Dick Schroeder
discusses incident w/
Sr Wentworth & Ken Bracken.



water forced sheet rock
away from wall.



265,000 BTU's were gener-
ated w/ space heaters ob-
tained from many sources
to dry out building.

Lucas locker room par-
ticular disappointment.



member of greens
crew surveys damage.




note condensation
on entrance windows



new furniture on
its way to replace
the damaged.



new insulation
installed through
out building.



Ladies lounge also
hard hit.



clean up crew
of 20



dance floor was
also ruined.